

info@ipmchico.com IPM PO BOX 1192

Phone: (530) 924-4365

PIR | Property Inspection Report

A PIR to be filled out each property visit, no less than once a month per property. It is an exterior inspection only, many times takes only a few minutes to walk the property.

Date/Time of Visit: 2016-04-06 14:43:23

Completed By: Andrew Quick

Property Address: 535 W. 4th Avenue, Chico, CA 95926, US

Time Spent (In Hours): 1 hours

Overall Condition of Property: 4

What did you do at the property?
Post Notice
Cleaned Laundry Room
✓ Pick Up Trash
Seeded/Fertilized
Sprayed Weeds
Night Inspection Other:
General Items in Need of Attention As you left it, things we need to correct
Missing Screens
Non-Operating Vechicles
Overflowing Mailboxes
Unpermitted Pets/Animals
Illegal Parking
Missing Doormats
General Trash
Broken/Missing Blinds
Paint Needed
Items to be Hauled
Disallowed Tenant Furniture
Broken/Burnt Lights
Party Evidence
Trailer/Boats/Other

Roof Debris Fence Repair Fascia Boards Need Paint Other:
Landscape Items In Need of Attention
Weeds
Leaf Pickup Needed
Broken Sprinklers/Adjustment
Mud
Downtree/Branches
Trash Overflowing
Dead Lawn Patches
Gutter Cleaning Needed
Bark Needed
Gravel Needed
Dead Plants
Tree Trimming Other:
Explanation and Other Items/Notes
Night Inspection: Dark areas. Add outdoor lights Replace Bulbs Other:

Document Pictures

IPM

535 & 545 W. 4th Avenue - Common
Ref #: 2016/04/06--14:43:23--PIR|PropertyInspectionReport, Date: 2016-04-06 14:47:20
535 W. 4th Avenue, Chico, CA 95926, US



Taken on: 2016-04-06 14:45:23 **Taken at:** 39.73795439, -121.85492968

Full resolution image



Taken on: 2016-04-06 14:45:32 **Taken at:** 39.73794935, -121.85488588 Full resolution image



Taken on: 2016-04-06 14:45:39 **Taken at:** 39.73793421, -121.85492185
Full resolution image



Taken on: 2016-04-06 14:45:56
Taken at: 39.73789347, -121.85500587
Full resolution image



Taken on: 2016-04-06 14:46:07
Taken at: 39.73783643, -121.85502978
Full resolution image